

# TrueMark Vehicle Inspections — Inspection Report

Inspect Before You Invest.  
 ABN: 53 384 207 098 · Sydney, NSW · 0423 636 633

## Vehicle

Plate: TEST99  
 VIN: TEST123456789  
 Odo: 95000  
 Date: 29/04/2026  
 Report ID: TM-20260429-TEST99-7

### Executive Summary

Toyota Hilux 2019

**SAFETY: PASS**

**VERDICT: PROCEED — MINOR ITEMS NOTED**

**Recommended: Only proceed if price is reduced by ~\$350-\$700**

**Deal Rating: 8.8/10 Good buy — minor items only, negotiate a small discount**

**Good buy — minor items noted but nothing that should stop the purchase if priced accordingly.**

Overall: **Good** Next service: **N/A**

Estimated spend exposure: **\$350-\$700**

**Buyer / Ownership Risk** 0.8/10

**LOW RISK**

**Vehicle Health** 91%

**STRONG**

**Inspection coverage:** 83% of fields captured · Confidence: 78%

### Section Dials

Quick visual health check by category.

#### Engine

Perfect



**OK**

Weighted score from inspection fields.

#### Road Test

Perfect



**OK**

Weighted score from inspection fields.

#### Tyres

Perfect



**OK**

Weighted score from inspection fields.

#### Brakes

Good



**OK**

Weighted score from inspection fields.

#### Underbody

Perfect



**OK**

Weighted score from inspection fields.

#### Electrical

Perfect



**OK**

Weighted score from inspection fields.

#### Interior

Perfect



**OK**

Weighted score from inspection fields.

#### Exterior

Perfect



**OK**

Weighted score from inspection fields.

#### Body

Not captured



**NOT CAPTURED**

Not captured in this inspection.

**Top Reasons**


- Brake pad condition — Brake pad wear directly affects stopping performance and is a safety-critical item.

**Tyre Depths (mm)**

Inner / Centre / Outer values per wheel.

**Tyre Position Map**

Colour shows overall tyre condition by tread depth and wear pattern.



**FRONT LEFT**

**4.0 mm**

OK

4.0

4.0

4.0

**FRONT RIGHT**

**4.0 mm**

OK

4.0

4.0

4.0

**REAR LEFT**

**5.0 mm**

OK

5.0

5.0

5.0

**REAR RIGHT**

**5.0 mm**

OK

5.0

5.0

5.0

Legend: Green = healthy tread and even wear. Amber = low tread or mild uneven wear. Red = critically low tread or severe uneven wear.

**Roadworthy**  
**PASS**

**Wet Grip**  
**PASS**

**Alignment**  
**PASS**

**Recommended Tyre Actions**

- No immediate tyre action required based on measured tread depths.

**Severity Guide**

- PASS — no immediate action required
- ATTENTION — plan repair soon
- FAIL — immediate action required

**Key Findings**

Buyer-focused summary designed to highlight repair leverage and likely ownership cost exposure.

Priority	Item	Status	Why it matters	Recommended action
<b>ATTENTION</b> MED COST	<b>Brake pad condition</b> Brakes	Requires attention	Brake pad wear directly affects stopping performance and is a safety-critical item.	Use this finding as negotiation leverage and obtain a repair quote before committing.

**Action Plan**

Minor items noted — vehicle is largely in good condition.

- The identified items are minor and manageable. Use them for a small price reduction.
- Confirm service history and proceed with standard due diligence.

**Estimated Repair Exposure**

\$350–\$700

- Use these findings as justification for a price reduction.
- Request the seller to repair the items or reduce the price accordingly.
- If the seller refuses, reassess whether the vehicle is still worth the adjusted risk.

**Negotiation Points**

- Brake pad condition (ATTENTION) — Cost: MED — Ask seller to fix or discount

**Questions / Booking**

Scan to book or ask questions.

<https://truemarkinspections.com.au/>

Need clarification? Message or call — happy to walk you through the report.

Report ID: TM-20260429-TEST99-7 · Hash: 6B9D025AE5 · Generated: 30/04/2026 09:31

Non-invasive inspection. Findings reflect observed condition at time of inspection.